


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-148	Smoke	11/19/2008	ADS/TM	S09OO1024MH	Dry	Yes	1,791.64



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-148	Smoke	11/19/2008	ADS/TM	S09001024MH	Dry	Yes	1,791.64

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S11001005G1	S11001005MH	S09001024MH	319.6287	10
S11001019G1	S11001019MH	S09001024MH	199.495	8
S11001017G1	S11001017MH	S11001019MH	90.11649	8
S11001001G1	S11001001MH	S11001017MH	103.9292	8
S11001003G1	S11001003MH	S11001017MH	93.40719	8
S11001020G1	S11001020MH	S11001003MH	164.8291	8
S11001025G1	S11001025MH	S11001020MH	113.2334	8
S11001031G1	S11001031DE	S11001035UN	122.1188	8
S11001033G1	S11001033DE	S11001035UN	88.56940	8
S09001005G1	S09001005MH	S09001024MH	305.3775	8
S09001024G1	S09001024MH	S09001016MH	190.9396	10

Observations & Photos

Obs_ID S1028-148-OB01

Address 4822 Palmer Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11001019MH

Comments Smoke from cleanout in front yard. 4822 Palmer Ave.



Picture \S1028-148-OB01-P01.jpg

Comments Front of house, 4822 Palmer Ave.

Obs_ID S1028-148-OB02

Address 4901 Palmer Ave


Status Private

Source Service Lateral

Location Yard - front

Nearest MH S09001024MH

Comments Smoke from service lateral in front yard 3 ft. from cleanout. 4901 Palmer Ave.



Picture \S1028-148-OB02-P01.jpg

Comments Smoke indicated by flag on the right. Front of house 4901 Palmer Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-148	Smoke	11/19/2008	ADS/TM	S09001024MH	Dry	Yes	1,791.64

Obs_ID S1028-148-OB03

Address 4901 Palmer Ave


Status Private

Source Service Lateral

Location Yard - front

Nearest MH S09001024MH

Comments Smoke from service lateral in front yard 1 ft. from cleanout. 4901 Palmer Ave.



Picture \S1028-148-OB03-P01.jpg

Comments Smoke indicated by flag on the left. Front of house, 4901 Palmer Ave.
